

1/4






Fig. 1

2/4

Status matrix									
File Help									
Status display	1	2	3	4	5	6	7	8	9
1 Measuring computer 28									
2 Measuring computer 30									
3 Measuring computer 32									
4 Measuring computer ...									
5 Measuring computer ...									
6 Measuring computer ...									
7 Measuring computer ...									
8 Measuring computer ...									
9 Measuring computer ...									

Fig. 2

Measuring computer 28 => Measuring computer 30						
	OWD (ms)	IPDV (ms)	PL (%)			
Best Effort	2.6	0.3	0			
TC 1	2.6	0.3	0			
TC 2	2.3	0.3	6.25			
Low Loss	2.3	0.3	0			
Best Effort	2.3	0.3	0			
TC 1	2.3	0.3	0			
TC 2	2.6	0.3	0			
Low Loss	2.3	0.3	0			
Best Effort	2.3	0.3	6.25			

58

60

62

64

Fig. 3

4/4




Fig. 4